

VILLAGE OF MORELAND HILLS

SEPTIC SYSTEM CONDITIONS ON BERKELEY AVE, ELLENDALE, AND WILTSHIRE ROADS



MAP
NOT TO SCALE

Legend

- 7% are updated to current Ohio code
- 63% approximately have an 50% chance of passing inspection
- 14% have a low chance of passing inspection - outdated design
- 16% have the lowest chance of passing inspection - antiquated design

Notes:
Information on condition of area septic systems provided by the Cuyahoga County Board of Health. May 18, 2016